Inspection report

HABA Group B. V. & Co. KG
Quality assurance

Subject:	2x Rumpelritter_NL
Item-No.:	2011721006
Production Code:	-
Packing unit:	PU=1
Manufacturer:	Modul
Supplier-no.:	10199
Task:	Compliance with quality requirements
Packing:	passed
EAN-Code check:	passed
Completeness:	passed
Quality of workmanship:	passed
Labelling:	passed
Rating:	passed
Comment:	

Bad Rodach	10.07.2025	Monja Morgenroth Quality Engineer